```
## North America Emission Control Area Fuel Oil Non-Availability Report
## ECA0100
## 1
##
##(Include Double Pound for comments, not form fields)
##Report Form ID
```

Ship Operator Name Vessel Name Flag Country Finaval S.p.A., via Galileo Galilei, 21 - 42024 Castelnovo Di Sotto - (RE) - Italy Isola Corallo Malta

IMO ID Number Date of ECA First Notice Location of ECA First Notice Name of Ports after First Notice 9396751 31-Dec-15 Lat 13 33.4 N, Long 066 18.7 W Lake Charles, LA

9 10

Aratu, Brazil

Name of Last Port before ECA Entry Name of Port with Fuel Oil Supply Disruption Lake Charles, LA

Name of Original Fuel Supplier with Disruption
Fuel is available but cannot be supplied, since the vessel cannot enter the channel to proceed
to Lake Charles, due to poor visibility.

Number of Fuel Suppliers Contacted Date of Entry in the ECA Time of Entry in the ECA 01 (One) 5-Jan-16 1435 hrs LT

15 16 17

Sulfur Content of Non-Compliant Fuel Oil Projected Hours on Main Propulsion Name of First POC 0.43% 7 hours Lake Charles, LA

Compliance Fuel Oil Available at First POC? Plan to Bunker Compliant Fuel Oil at First POC? Yes Yes (delayed due to fog and poor visibility)

Number of fuel suppliers contacted at First POC Name of Second POC Compliant Fuel Oil at Second POC? 1 (One) NA NA

Plan to Bunker Compliance Fuel Oil at Second POC? Number of Fuel Suppliers Contacted at the Second POC? NA

Date of Exit from ECA? Time of Exit from ECA? Has this vessel operated in the ECA in previous 12 months?

12-Jan-16 1200 hrs LT Yes

Number of Separate Visits to the ECA 
Number of Ports visited in the ECA 
Previously submitted ECA0100 forms? 
O5 (Five) 
O7 (Seven) 
Yes, 23 May 2013

01 (One)

Number of Submitted Reports Designated Corporate Official Name Designated Corporate Official E-mail Capt. Francesco Sabia

operations@finaval.com

Designated Corporate Official Phone Number 0039 3346016136

Description of Actions to Achieve Compliance

Vessel is currently at Lake Charles anchorage, burning compliant fuel (LSMGO).

Plans have been made to receive more compliant fuel at berth, but due to channel closure in restricted visibility, the vessel's berthing schedule has been delayed indefinitely. Current reserves of compliant fuel will run out on January 10, 2016 after which the vessel will be forced to use non-compliant fuel until berthing is permitted.